Pro2 Motion Board Cooling Fan Installation Instruction

STEP 1: Power Off

Turn off the printer $_{\circ}$



STEP 2: Remove the cover of the electronic box

Pull the cover out at the top left corner by hand gently and insert a flat head screwdriver to remove the cover.





WWW.RAISE3D.COM AMERICA · ASIA · EUROPE

STEP 3: Remove the Old Fan

Remove the two fixing screws and unplug the connector of its cable from the Motion Controller Board. Take the old fan off



STEP 4: Install the New Fan

Install the new fan into the electronic box. Put the screws and washers back and tighten the screws to fix the fan.

Plug the connector of the new fan to the terminal where you unplug the old fan from.



